## Work Order ID 56740

March 5, 2010 9:59:52 AM



Page 1

Item ID:

D412-742-015

Accept

Setup Start

Stop

Revision ID:

Start Date:

Item Name: Electric Step

**Required Date: 17/03/2010** 

05/03/2010

QC:

Start Qty: 2.00

Req'd Qty: 2.00



**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

Process Plan:

Date://2-3-Tooling:

Date: SPC (Y/N):

Date:

Date:

Run Start

Stop

Sequence ID/ **Work Center ID** 

Operation

Description

Set Up/ **Run Hours**  Draw Number Draw Plan Rev. Code

Reject Accept Qty

Qty

Reject Insp. Number Stamp

**Draw Nbr** N/A

**Revision Nbr** Rev D

100

Document Control

DOCUMENT CONTROL

0.00 Memo Photocopy bluefile & type labels per PPPD412-742-015

110

Packaging Packaging

Pick Kit

0.00

0.00

Memo

0.00

10-6-30

120

0.00

0.00

Quality Control

Memo

QC4- 100% Inspect kits for completeness

## **Dart Aerospace Ltd** W/O: WORK ORDER CHANGES Approval **Approval** DATE **STEP** PROCEDURE CHANGE Bv Qtv Date Chief Eng / QC Inspector Prod Mar s Part No: \_\_\_\_\_\_ PAR #: \_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_ Date: \_\_\_\_\_ Resolution: \_\_\_\_\_ Disposition: \_\_\_\_ QA: N/C Closed: \_\_\_ Date: **WORK ORDER NON-CONFORMANCE (NCR)** NCR: **Corrective Action** Section B **Description of NC** Verification DATE **STEP** Approval Approval Sign & **Action Description** Initial Section A Section C Chief Ena QC Inspector Chief Eng Chief Eng Date

## Work Order ID 56740

March 5, 2010 9:59:52 AM



Page 2

Item ID:

D412-742-015

Accept



Setup Start

Stop



Revision ID:

**Start Date:** 

Item Name: Electric Step

05/03/2010

Start Qty: 2.00

**Required Date: 17/03/2010** 

Req'd Qty: 2.00



**Cust Item ID: Customer:** 

Draw

Number

Reference:

An	provals:	
7 x p	pi ovais.	

Process Plan:

QC:

Date:\_\_\_\_\_

Date:\_\_\_\_ Tooling:

SPC (Y/N):

Date:

Date:

Draw

Rev.

Plan

Code

Sequence ID/

**Work Center ID** 

130

Packaging

Packaging

Operation

**Description** 

Set Up/ **Run Hours** 

0.00

0.00

Packaging

Memo

Identify and pack for shipping as per PPP D412-742-015

140

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

Run

Accept

Qty

Start



Stop

Insp. Reject

Number Stamp

Reject

Qty

10/06/30 945 MK 10-6-30

Dart	<b>Aeros</b>	pace	Ltd
------	--------------	------	-----

W/O:			W	ORK ORDER CHANG	GES					<u> </u>
DATE	STEP	PRO	CEDURE CH	IANGE		Ву	Date	Oty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
										•
Part No		PAR #:								
	R	esolution:	Disposit	ion:	QA:	N/C Clo	sed:		Date:	
NCR:		\	WORK OR	DER NON-CONFORM	IANCE	(NCR)				
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Sec Action Description Chief Eng	ction B	Sign & Date	Verifica Section		Approval Chief Eng	Approval QC Inspector
			Office Ling	Onlet Eng		Date				-
									: :	
NOTE										

## **Picklist Print**

March 5, 2010 9:59:51 AM

Work Order ID: 56740

Parent Item: D412-

D412-742-015

Parent Item Name:

Electric Step

Comments:

· ·

IPP Rev:A New Issue 07-05-023 JLM

Purchased

No



Start Date: 05/03/2010

**Required Date: 17/03/2010** 

Start Qty: 2.00

Required Qty: 2.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status	
D2913		Manufactured	No			120	Each	24.0000	2.0000				_

Warehouse Location

Main Warehouse

ST030 13440 24 12

12 120 Each

Loc Oty

374.0000 4.0000

Loc Code

10.630 5

10-6-30

(<del>2</del>5)

MS21043-4 XZ

M114348 Warehouse Loc Qty Loc Code Location OFFSHORE FG 40 104603 40 Main Warehouse ST 334 112314 100 112492 11 113064 223

## **Dart Aerospace Ltd** W/O: **WORK ORDER CHANGES Approval** DATE **Approval STEP PROCEDURE CHANGE** By Qty Date Chief Eng / QC Inspector Prod Mgr Part No: \_\_\_\_\_\_ PAR #: \_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_ Date: \_\_\_\_\_ Resolution: \_\_\_\_\_ Disposition: \_\_\_\_ QA: N/C Closed: \_\_\_ Date: \_\_\_\_\_ **WORK ORDER NON-CONFORMANCE (NCR)** NCR: **Corrective Action** Section B **Description of NC** Verification **Approval** DATE **STEP** Approval **Action Description** Sign & Initial Section A Section C Chief Eng QC Inspector Chief Eng Chief Eng Date

March 5, 2010 9:59:51 AM

Work Order ID: 56740

Parent Item:

D412-742-015

Parent Item Name: Electric Step

**Comments:** 

IPP Rev:A New Issue 07-05-023 JLM

Start Date: 05/03/2010

Required Date: 17/03/2010

Start Qty: 2.00

Required Oty: 2.00

Component Item ID/	Replacement	Mfg/	Bin Primary	Last	Route	Unit of	Qty on	Remaining	Qty	Date	Status
Item Name	Item ID	Purch	Item Location	Location	Seq ID	Measure	Hand	Qty To Pick	Issued	Issued	
MS24693-C272		Purchased	No		120	Each	1,392.000	4.0000		^	

Warehouse	
<b>Location</b>	
Main Wand	

9370

Main Warehouse ST 1392 519 17831 520 8814 3 8815 31 9063 19

Loc Qty

MS35489-35

Purchased

No

120

300 Each

22.0000 2.0000

Loc Code

Loc Code

<u>Warehouse</u>	Loc Oty
<b>Location</b>	
Main Warehouse	
ST	22
6880	22

Dart Aerospace L	_td
------------------	-----

W/O:			V	ORK ORDER CHANG	FS			╁		1
DATE	STEP	PROC	CEDURE CH			Ву	Date	ety	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No		PAR #:							Date:	
	R	esolution:	_ Disposit	ion:	_ QA: I	VC Clo	sed:		Date:	
NCR:		W	ORK OR	DER NON-CONFORMA	NCE	(NCR)				
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng		Sign & Date	Verificat Section		Approval Chief Eng	Approval QC Inspector
										-
					1					
								!		

March 5, 2010 9:59:51 AM

Work Order ID: 56740

Parent Item:

D412-742-015

Parent Item Name:

Electric Step

Comments:

IPP Rev:A New Issue 07-05-023 JLM



Start Date: 05/03/2010

**Required Date: 17/03/2010** 

Start Otv: 2.00

Required Oty: 2.00

Component Item ID/ Item Name

Replacement Mfg/ Item ID

Purch

Purchased

Bin Primary Item Location

No

Last Location Route Seq ID

120

Unit of Otv on Measure Hand

Remaining Oty To Pick Qty Issued

Date Issued

Status

MS35489-93

GROMMET

Loc Otv

Loc Code

126.0000 2.0000

Warehouse Location Main Warehouse ST

113368 114108 126 26

100

Each

	-									
W/O:			W	ORK ORDER CHAI	NGES		<del></del>			•
DATE	STEP	PRO	OCEDURE CH	IANGE		Ву	Date	qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
										c.
Part No		PAR #:							Date:	
	R	esolution:	Disposit	ion:	QA:	N/C Clo	sed:		Date: _	
NCR:		,	WORK OR	DER NON-CONFOR	MANCE	(NCR	)			
DATE STEP Description of NC		Description of NC			Section B	V6			Approval	Approval
	JILI	Section A	Initial Chief Eng	Action Description Chief Eng	on	Sign & Date	Verification Section C		Chief Eng	QC Inspector
										-
						-			·	
·										
								·		
-		*								,
	L	1	ŀ							

# REFERENCE ONLY

## DART AEROSPACE USA, INC.

IIN-D412-742 Page 16 of 20



#### 5.0 **PARTS LIST**

### D412-742-011 (PMA/OEM) Float Skidtube Installation Parts List 5.1

Item	Qty -011	Qty -041	Qty -015	Part Number	Description
	Х			D412-742-011	FLOAT SKIDTUBE INSTALLATION
	1	Х		D412-742-041	FLOAT SKIDTUBE
	1		Х	D412-742-015	ELECTRIC STEP KIT
		1		D3391-041	412 FLOAT SKIDTUBE
1		*24		*AN3C4A	*BOLT
3		*12		*AN3C6A	*BOLT
4		*8		*AN3C7A	*BOLT
5	, -	*44		*AN960C10L	*WASHER
6		*4		*MS27039C4-12	*SCREW
7A		*4		*D3672-3	*WASHER (REPLACES NAS1515H4L)
7B		*4		*AN960C416L	*WASHER
21A		*1		*D3564-1	*WEARSHOE (REPLACES D3460-1)
21B		*1		*D3566-1	*GASKET
22A		*1		*D3564-3	*WEARSHOE (REPLACES D3460-3)
22B		*1		*D3566-1	*GASKET
23A		*1	-	*D3564-5	*WEARSHOE (REPLACES D2577-5)
23B		*1		*D3566-5	*GASKET
200		<u> </u>			
10		*1		*D3391-011	*412 FORWARD TUBE
11		**1	<del> </del>	**D3401-041	**TOW CAP
12A		**10		**AELS-1032-225	**INSERT (REPLACES NAS1330S3KB166)
12B	<del>                                     </del>	**2		**AELS-1032-130	**INSERT (REPLACES NAS1330S3KB166)
13		**10		**AN3C4A	**BOLT
14A		**4		**D3672-1	**WASHER (REPLACES NAS1515H3L)
14B		**10		**AN960C10L	**WASHER
24A		**1		**D3564-13	**WEARSHOE
24B	<del> </del>	**1		**D3566-13	**GASKET
20	<del></del>	*1		*D3391-013	*412 MID TUBE
28		**24		**AELS-1032-130	**INSERT (REPLACES NAS1330S3KB116)
	<u> </u>	<del>                                     </del>			
30	<del> </del>	*1		*D3391-015	*412 AFT TUBE
25A		**1		**D3537-1	**WEARPAD
25B	_	**1		**D3553-1	**GASKET
26A	<del>                                     </del>	**1		**D3537-7	**WEARPAD
26B		**1	-	**D3553-3	**GASKET
31	<u> </u>	**1		**D2646	**AFT CAP
32	<del>                                     </del>	**14	<del> </del>	**AELS-1032-130	**INSERT
36	<u> </u>	**12	-	**AELS-1032-225	**INSERT (REPLACES NAS1330S3KB366)
37A	<del>                                     </del>	**6		**AN3C4A	**BOLT
37B	<del> </del>	**4	<del>                                     </del>	**AN3C5A	**BOLT
38A	<del> </del>	**2		**D3672-1	**WASHER (REPLACES NAS1515H3L)
38B	<del>                                     </del>	**10	<del>                                     </del>	**AN960C10L	**WASHER
39	<del>                                     </del>	**4	<del> </del>	**ALS4-428-165	**INSERT (REPLACES NAS1330S4KB151)
39	<u> </u>		1	(CONTINUED OF	

(CONTINUED ON PAGE 17)

• COPYRIGHT © 2005 BY DART AEROSPACE USA, INC •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

Revision: **D** 

Date: 07.10.04



## DART AEROSPACE USA, INC.

IIN-D412-742 Page 17 of 20

(CONTINUED FROM PAGE 16)

Item	Qty -011	Qty -041	Qty -015	Part Number	Description
40	1			D2571	SADDLE, FWD OUTSIDE
41	1			D2572	SADDLE, FWD INSIDE
42	1			D2573	SADDLE, AFT OUTSIDE
43	1			D2574	SADDLE, AFT INSIDE
44	2			D2876	SADDLE SPACER
45	2			D2877	SADDLE SPACER
46	16			D3403-1	BUSHING
47A	4			D2747	SET SCREW
47B	2			D3533-1	SET SCREW
48	16			AN4C6A	BOLT
49	8			AN4C52A	BOLT
50	8	_		AN6C12A	BOLT
51A	32			D3672-3	WASHER (REPLACES NAS1515H4L)
51B	32	_		AN960C416L	WASHER
52A	8			D3672-9	WASHER (REPLACES NAS1515H6L)
52B	8			AN960C616L	WASHER
53	16			D3672-11	WASHER (REPLACES NAS1515H7L)
54	24			MS21043-4	NUT
55	4			AN4C7A	BOLT
					PLICHING
60	8			D3403-3	BUSHING
61	1			D3405-041	GHW LUG
62	1			D3405-043	GHW LUG
63	4			AN4C46A	BOLT
64	4			MS21043-4	NUT
70	1			D3407-041	TOW RING
71	2		•	D3417-3	WASHER
72	1			MS21043-4	NUT
73	1			D3456-1	WASHER
			1	D2913	DOUBLER
80		***4	1	***ALS4-428-165	***INSERT (REPLACES NAS1329S4KB140)
81		***4		***AELS-1032-130	***INSERT (REPLACES NAS1330S3KB116)
82	ļ	4		MS21043-4	NUT
83			2	MS24693-C272	SCREW
84				MS35489-35	GROMMET
85	<del></del>		1 1	MS35489-93	GROMMET
86		***4	<del>                                     </del>	***MS27039C1-09	***SCREW
87		***4		***MS27039C4-08	***SCREW
88		***4	2	***D3672-1	***WASHER (REPLACES NAS1515H3L)
89A		***4	2	***AN960C10L	***WASHER
89B 90A		***4		***D3672-3	***WASHER (REPLACES NAS1515H4L)
		***4	<del> </del>	***AN960C416L	***WASHER
90B		-4		AN900C410L	VVACILIX
91	3			AN3C37A	BOLT
92	22	ļ		AN3C40A	BOLT
93	3			AN3C41A	BOLT
94	3			AN3C42A	BOŁT
95	3			AN3C43A	BOLT
96	9			AN3C44A	BOLT
98	10			AN3C47A	BOLT
99	66			AN960C10L	WASHER
100	33			MS21043-3	NUT

\*DENOTES PART IS INCLUDED WITH D3391-041 ASSEMBLY ABOVE

\*\*DENOTES THAT PART IS INCLUDED ABOVE ASSEMBLY

\*\*\*DENOTES THAT PART IS INCLUDED WITH D3391-013

• COPYRIGHT © 2005 BY DART AEROSPACE USA, INC •
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE USA, INC.

Revision: **D** 

Date: 07.10.04